



TECHNICAL BULLETIN

No: LTB00105
Issue: 1
Date: 22 JAN 2008

CIRCULATE: TO

Service Mgr
X

Warranty
X

Workshop
X

Body Shop

Parts

SECTION: 211

New Workshop Procedure: Steering Gear Removal / Installation

AFFECTED VEHICLE RANGE:

LR3 (LA)

VIN: 5A000360 - Onwards
Model Year: 2005 - Onwards

Range Rover Sport (LS)

VIN: 6A900290 - Onwards
Model Year: 2006 - Onwards

CONDITION SUMMARY:

NEW WORKSHOP PROCEDURE: STEERING GEAR REMOVAL/INSTALLATION

Situation: A new workshop procedure has been developed for the removal and installation of the steering gear. It is no longer necessary to remove the road wheels or track rod ends.

Action: In the event a retailer should have to remove/install the steering, follow the Repair Procedure outlined below.

WARRANTY:



NOTE: Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to DDW to obtain the latest repair time.

DDW requires the use of causal part numbers. Labor only claims must show the causal part number with a quantity of zero.

Description	SRO	Old Time (Hours)	New Time (Hours)
LR3 - Remove/install the steering gear (AJV8)	57.10.01	1.30	1.00
LR3 - Remove/install the steering gear (V6 Cologne)	57.10.01	1.10	0.90
Range Rover Sport - Remove/install the steering gear (AJV8 N/A)	57.10.01	1.40	1.00
Range Rover Sport - Remove/install the steering gear (AJV8 SC)	57.10.01	1.60	1.30

Normal warranty policy and procedures apply.

REPAIR PROCEDURE

REMOVAL AND INSTALLATION: STEERING GEAR



NOTE: GLOBAL TECHNICAL REFERENCE (GTR) LOOKUP SEQUENCE IS AS FOLLOWS:
GTR HOME > NAS > MODEL > CHASSIS > WORKSHOP MANUAL > 211: STEERING SYSTEM > 211-02: POWER STEERING

1. Refer to Workshop Manual (GTR) section 211-02: Power Steering for the revised removal/installation instructions.

NOTE: The information in Technical Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers." If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether the bulletin applies to a specific vehicle.