



# TECHNICAL BULLETIN

No: LTB00119  
Issue: 1  
Date: 10 MAR 2008

CIRCULATE: TO

Service Mgr  
X

Warranty  
X

Workshop  
X

Body Shop

Parts

## SECTION: 303

# Revised Workshop Procedure - Remove / Install Engine and Ancillaries

## AFFECTED VEHICLE RANGE:

LR3 (LA) 4.4L V8 Only

VIN: 5A000360 - Onwards  
Model Year: 2005 - Onwards

## CONDITION SUMMARY:

**Situation:** The removal / installation procedure for 4.4L V8 engine and ancillaries has been revised. The removal of the right-hand driveshaft, engine compartment cover and radiator is no longer required as there is adequate clearance between the engine oil pan and driveshaft for the engine to be moved forward before lifting.

**Action:** When removing / installing the engine and ancillaries, refer to the revised Repair Procedure as outlined below

## PARTS:

No parts required

## TOOLS:

No special tools required

## WARRANTY:



**NOTE:** Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to DDW to obtain the latest repair time. Other SROs affected by this procedure will also change.

DDW requires the use of causal part numbers. Labor only claims must show the causal part number with a quantity of zero.

Description	SRO	Old Time (Hours)	New Time (Hours)
Engine and ancillaries - remove for access	12.41.01/99	11.20	7.60
Stripped engine - remove engine, change over ancillary equipment and install	12.41.02	14.20	10.6
Crankshaft main bearing carrier - remove and install	12.21.42	17.50	13.9

*Normal warranty policy and procedures apply.*

## REPAIR PROCEDURE

### REMOVING / INSTALLING ENGINE (4.4L)



**NOTE:** Global Technical Reference (GTR) lookup sequence is as follows:  
GTR Home > NAS > LA - LR3> Service Information > Model Year > Workshop Manuals > 3:  
Powertrain > 301-01B: Engine 4.4L

1. Refer to Workshop Manual (GTR) Section 301-01B: Engine 4.4L for the removal / installation procedure

<p><b>NOTE:</b> The information in Technical Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers." If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether the bulletin applies to a specific vehicle.</p>
---