



TECHNICAL BULLETIN

No: LTB00156
Issue: 1
Date: 22 July 2008

CIRCULATE: TO

Service Mgr
X

Warranty
X

Workshop
X

Body Shop
X

Parts

SECTION: 303

Workshop Manual Update - Remove / Install Expansion Tank

AFFECTED VEHICLE RANGE:

LR3 (LA)

VIN: 5A000360 - Onwards

Model Year: 2005 - Onwards

Range Rover Sport (LS)

VIN: 6A900129 - Onwards

Model Year: 2006 - Onwards

CONDITION SUMMARY:

Situation: The Workshop Manual procedure for the removal / installation of the expansion tank has changed. The new procedure includes the removal of the headlamp and front grille to allow access to the expansion tank lower pipes.

Action: In the event it becomes necessary to remove / install the expansion tank, follow the revised Repair Procedure outlined below.

PARTS:

No parts necessary; informational purposes only

TOOLS:

Refer to Workshop Manual (GTR) for any special tools (if required)

WARRANTY:



NOTE: Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to DDW to obtain the latest repair time.

DDW requires the use of causal part numbers. Labor only claims must show the causal part number with a quantity of zero.

Description	SRO	Old Time (hours)	New Time (hours)
Tank - Renew - LR3 (4.0L V6)	26.15.01	0.40	0.40
Tank - Renew - LR3 (4.4L V8)		0.50	
Tank - Renew - Range Rover Sport (4.2L V8)		0.40	
Tank - Renew - Range Rover Sport (4.4L V8)		0.40	

Normal warranty policy and procedures apply.

REPAIR PROCEDURE

REMOVE / INSTALL EXPANSION TANK



NOTE: Global Technical Reference (GTR) lookup sequence is as follows:

GTR Home > NAS > Model > Service Information > Model Year > Workshop Manual > 3: Powertrain > 303: Engine

1. Refer to Workshop Manual (GTR) Section 303-03 (26.15.01) to remove / install the expansion tank.

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether the bulletin applies to a specific vehicle.