SECTION: 415

New Workshop Procedure - Remove / Install DVD Autochanger AFFECTED VEHICLE RANGE:

LR3 (LA) VIN: 5A000360 - Onwards

Model Year: 2005 - Onwards

Range Rover Sport (LS) VIN: 6A900129 - Onwards

Model Year: 2006 - Onwards

CONDITION SUMMARY:

Situation: A new workshop procedure has been developed for the removal / installation of the DVD autochanger.

Action: In the event it becomes necessary to remove / install the DVD autochanger, refer to the Repair Procedure outlined below.

PARTS:

No parts necessary

TOOLS:

Refer to the Workshop Manual (GTR) for any required special tools

WARRANTY:

NOTE: Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to DDW to obtain the latest repair time

DDW requires the use of causal part numbers. Labor only claims must show the causal part number with a quantity of zero.

Description	SRO	Time (hours)
DVD Autochanger - Renew	86.50.59	0.50

Normal warranty policy and procedures apply.

REPAIR PROCEDURE

NOTE: Global Technical Reference (GTR) lookup sequence is as follows:
GTR Home > NAS > Model > Service Information > Model Year > Workshop Manual >
4: Electrical > 415: Information and Entertainment Systems > 415-07: Video System

1. Refer to Workshop Manual (GTR) Section 415-07: Video System to remove / install the DVD Autochanger.

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether this bulletin applies to a specific vehicle.