Reference SSM47477

Range Rover Sport / L320

Models LR3 / L319

Range Rover / L322

Title 4.4 Naturally Aspirated AJV8 Petrol Oil Filter/Housing Leaks

Category Engine

Last modified 31-Jan-2011 00:00:00

Symptom 401000 Oil System Concerns

<u>lssue:</u>

Land Rover Engineering have been investigating reports of engine oil leaking in the vicinity of the oil filter assembly shortly after replacement during routine service work on the 4.4 N/A AJV8 engine.

Cause:

All alleged leaking oil filters returned for testing have been found to be negative for leaks when witness tested with Content the supplier.

Action:

If the above stated issue is verified Land Rover recommend that the oil cooler assembly and oil filter are replaced simultaneously.

Parts Information

Oil Cooler – 4526544 Oil Filter – LR007160