Work Order: Last Name: R000025 SN06 KYR

Registration:

SN06 KYR

Technician: Odometer:

MARCIN


75503

Date


26.6.14 8:44

Land Rover: Discovery: 2005-09 (Series III): with Dynamic Air Suspension: Right-hand Drive


Before Measurements






















Excessive Thrust Angle could cause a crooked steering wheel.





This vehicle's Steering Angle Sensor may require calibration using an OEM scan tool after alignment.