



TECHNICAL BULLETIN

No: LTB00125
Issue: 1
Date: 14 MAR 2008

CIRCULATE: TO

Service Mgr
X

Warranty
X

Workshop
X

Body Shop

Parts
X

SECTION: 303

4.4L V8 'Short' Engine Availability

AFFECTED VEHICLE RANGE:

LR3 (LA) 4.4L V8

VIN: 5A000360 - Onwards

Model Year: 2005 - Onwards

CONDITION SUMMARY:

Situation: A 4.4L V8 'short' engine is now available as a serviceable part for engine bottom-end repairs that require engine replacement.

Action: To install a new short engine, refer to the new Repair Procedure outlined below.

PARTS:

LR004705Short Engine Qty: 1

TOOLS:

Refer to Workshop Manual (GTR) for any special tools that may be required.

WARRANTY:



NOTE: Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to DDW to obtain the latest repair time.

DDW requires the use of causal part numbers. Labor only claims must show the causal part number with a quantity of zero.

| Description | SRO | Time (Hours) |
|-------------------------------|----------|--------------|
| Short Engine Assembly - Renew | 12.41.04 | 16.70 |

Normal warranty policy and procedures apply.

REPAIR PROCEDURE

REPLACING 'SHORT' ENGINE (4.4L)



NOTE: Global Technical Reference (GTR) lookup sequence is as follows:

GTR Home > NAS > LA - LR3> Service Information > Model Year > Workshop Manuals > 3: Powertrain > 301-01B: Engine 4.4L

1. Refer to Workshop Manual (GTR) Section 301-01B: Engine 4.4L for the removal / installation procedure.

NOTE: The information in Technical Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers." If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether the bulletin applies to a specific vehicle.