



TECHNICAL BULLETIN

No: LTB00145
Issue: 1
Date: 13 MAY 2008

CIRCULATE: TO

Service Mgr
X

Warranty
X

Workshop
X

Body Shop
X

Parts

SECTION: 206

Revised Workshop Procedure - Remove / Install Parking Brake Cables

AFFECTED VEHICLE RANGE:

LR3 (LA)

VIN: 5A000360 - Onwards
Model Year: 2005 - Onwards

Range Rover Sport (LS)

VIN: 6A900129 - Onwards
Model Year: 2006 - Onwards

CONDITION SUMMARY:

Situation: Revised workshop procedures have been developed for the removal and installation of the parking brake cables. In the new procedures, the electronic park brake actuator remains in position and the cables are removed through the wheel arch.

Action: When removing / installing the parking brake cables, refer to the Repair Procedure outlined below.

PARTS:

No parts required

WARRANTY:



NOTE: Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to DDW to obtain the latest repair time.

DDW requires the use of causal part numbers. Labor only claims must show the causal part number with a quantity of zero.

Description	SRO)	Old Time (hours)	New Time (hours)
Cable Assemblies - Parking Brake - Set - Renew (LR3)	70.35.16	2.40	1.30
Cable - Parking Brake - RH - Renew (LR3)	70.35.30	2.40	0.80
Cable - Parking Brake - LH - Renew (LR3)	70.35.31	2.20	0.80
Cable Assemblies - Parking Brake - Set - Renew (Range Rover Sport [Supercharged])	70.35.16	2.40	1.30
Cable - Parking Brake - RH - Renew (Range Rover Sport [Supercharged])	70.35.30	2.30	0.80
Cable - Parking Brake - LH - Renew (Range Rover Sport [Supercharged])	70.35.31	2.30	0.80
Cable Assemblies - Parking Brake - Set - Renew (Range Rover Sport [Naturally Aspirated])	70.35.16	2.30	1.30
Cable - Parking Brake - RH - Renew (Range Rover Sport [Naturally Aspirated])	70.35.30	2.30	0.80
Cable - Parking Brake - LH - Renew (Range Rover Sport [Naturally Aspirated])	70.35.31	2.40	0.80

Normal warranty policy and procedures apply.

NOTE: The information in Technical Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers." If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether the bulletin applies to a specific vehicle.



REPAIR PROCEDURE



**NOTE: Global Technical Reference (GTR) lookup sequence is as follows:
GTR Home > NAS > Model > Service Information > Model Year > Workshop Manuals >
2: Chassis > 206: Brake System > 206-05: Parking Brake and Actuation**

1. Refer to Workshop Manual (GTR) Section 206-05: Parking Brake and Actuation for the revised removal / installation procedures.