

TECHNICAL BULLETIN

No: LTB00360 (ISSUE 1)
18 FEB 2011

RANGE ROVER



CIRCULATE TO: SERVICE ✓ PARTS ✓ WARRANTY ✓ BODY SHOP ✓

SECTION: 501

Front Seat Rail - Lower Level Service Repair

AFFECTED VEHICLE RANGE:

LR2 (LF)	VIN: 8H000212 - Onwards Model Year: 2008 - Onwards
LR3 (LA)	VIN: 5A000360 - 9A513325 Model Year: 2005 - 2009
LR4 (LA)	VIN: AA510742 - Onwards Model Year: 2010 - Onwards
Range Rover Sport (LS)	VIN: 6A900290 - 7A999999 7A100000 - Onwards Model Year: 2006 - Onwards

CONDITION SUMMARY:

Situation: A lower level service repair is now available in the event it is necessary to replace a front seat rail; it is no longer necessary to replace the complete front seat lower frame.

Action: In the event of a customer concern of the above, refer to the Repair Procedure outlined below to replace the front seat rails.

PARTS:

LR023396Seat rail set Qty: 1

TOOLS:

Refer to Workshop Manual for any required special tools

WARRANTY:



NOTE: Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to DDW to obtain the latest repair time.

DDW requires the use of causal part numbers. Labor only claims must show the causal part number with a quantity of zero.

DESCRIPTION	SRO	TIME (HOURS)	CONDITION CODE	CAUSAL PART
Front seat rail - set - Renew LR2	78.70.69	0.80	42	LR012040 (non-memory seats) LR012041 (memory seats)
Front seat rail - set - Renew LR3, LR4, Range Rover Sport	78.70.69	0.90		

Normal Warranty policies and procedures apply.

REPAIR PROCEDURE

1. Refer to Workshop Manual, section 501-10: Seating, and replace the front seat rail set.

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether this bulletin applies to a specific vehicle.