

Lookers Chelmsford Land Rover Cuton Hall Lane Chelmsford Essex CM2 5PX

Telephone: 01245 611 111 Facsimilie: 01245 611 133



CASH SALE INVOICE

Inv. Printed By: Gary McKay

Inv. Created By: Kate Stephenson

Account No.	Document Nu	mber	Date & Tax Point	Order Number		Route	
C6402	6030586	7	19/02/2009				11.00.170
Make & Mod	el	CI	nassis No.	Engine No.	Mileage	Time I	Page
DISCOVERY 3 2.7	7 TDV6 SE	SALLAA	A175A312154	1111040017618276DT	36895	13:28	1
Reference No.		Reg No.	Reg Date	VSB No. W	I.P. No.	Job No).
		S16MUD	04/03/2005	W	34123	832	26

Lookers Wholesale event is now started, Please ask for detai about our FANTASTIC deals on New & Used Vehicles

A 101061 sk64 60,000 miles/ 96,000 km or 48 months service Quoted £ 294.00 inc vat inc allegiance discount X L1013938 PLUG - OIL DRAIN 1.00 2.30 X L1311289 ELEMENT - OIL CO 1.00 8.27 X LJKR500020 FILTER ASSY 1.00 29.71 X LLR010075 KIT - FUEL FILTE 1.00 55.55 P PSS1 BULK Shell Helix Ult 6.00 12.33 T NOTES 1.Check front suspension bushes and joints for excessive wear none detected at time of inspection 2.Renewed high tone horn under ext warranty	EACH EPY EACH FPY EACH FVY	1.84 6.62 23.77 44.44 54.75 0.00
X L1013938 PLUG - OIL DRAIN 1.00 2.30 X L1311289 ELEMENT - OIL CO 1.00 8.27 X LJKR500020 FILTER ASSY 1.00 29.71 X LLR010075 KIT - FUEL FILTE 1.00 55.55 P PSS1 BULK Shell Helix Ult 6.00 12.33 T NOTES 1.Check front suspension bushes and joints for excessive wear none detected at time of inspection 2.Renewed high tone horn under ext warranty	EACH EPY EACH FPY EACH FVY	6.62 23.77 44.44 54.75
X L1311289 ELEMENT - OIL CO 1.00 8.27 X LJKR500020 FILTER ASSY 1.00 29.71 X LLR010075 KIT - FUEL FILTE 1.00 55.55 P PSS1 BULK Shell Helix Ult 6.00 12.33 T NOTES 1.Check front suspension bushes and joints for excessive wear none detected at time of inspection 2.Renewed high tone horn under ext warranty	EACH EPY EACH FPY EACH FVY	23.77 44.44 54.75
X LJKR500020 FILTER ASSY 1.00 29.71 X LLR010075 KIT - FUEL FILTE PSS1 BULK Shell Helix Ult T NOTES 1.Check front suspension bushes and joints for excessive wear none detected at time of inspection 2.Renewed high tone horn under ext warranty	EACH FVY	44.44 54.75
X LLR010075 KIT - FUEL FILTE P PSS1 BULK Shell Helix Ult T NOTES 1.Check front suspension bushes and joints for excessive wear none detected at time of inspection 2.Renewed high tone horn under ext warranty	300. —300.——	54.75
T NOTES 1. Check front suspension bushes and joints for excessive wear none detected at time of inspection 2. Renewed high tone horn under ext warranty	EACH	
1.Check front suspension bushes and joints for excessive wear none detected at time of inspection 2.Renewed high tone horn under ext warranty		0.00
excessive wear none detected at time of inspection 2.Renewed high tone horn under ext warranty		
inspection 2.Renewed high tone horn under ext warranty		
2.Renewed high tone horn under ext warranty		
**·		
3 		
	,	
		Ì
	*	

			٧	Rate	Service/Goods	VAT	Net	256.42
	Parts	131.42	s	15.00	256.42	38.46	V.A.T.	38.46
	Surcharge	0.00					Total	294.88
@ .	Labour	125.00				ŀ	Paid	0.00
E	Sublet	0.00				<u> </u>	Owing	294.88
© F & O F	Menus	0.00					Y", T'' Y	

Next Service Date 17/02/2010

Next MOT Date 01/02/2009