


[Click here to print](#)

Connector: **C1699**

CONNECTOR HOUSING NOT SERVICEABLE



BLACK

Part No.: **YPC909530**

Colour: **BLACK**


Cavities: **3WY**

Harness: **CHASSIS HARNESS**

Description: **Sensor-Height-Rear-LH**

Location: **Below LH rear wheelarch**

Qualifier:



Wire Chart and Service Repair Kit Information

CAV	CSA	COL	CCT	DESTN	Pre-Terminated Lead	Extract Tool	Applicator	Wire Stripper	Heat Shrink Sleeve	Ident Sleeve	Splice
1	0.5D	OY	419	C0391	418-549-11	-	418-116A	418-117	418-104	418-112	418-107
4	0.5D	OR	419	C0391	418-549-11	-	418-116A	418-117	418-104	418-112	418-107
5	0.5D	OB	419	C0391	418-549-11	-	418-116A	418-117	418-104	418-112	418-107

Connector: **C1699**

CONNECTOR HOUSING NOT SERVICEABLE

Description: **Sensor-Height-Rear-LH**

Location: **Below LH rear wheelarch**

Qualifier: